CRITICAL ITEMS LIST (CIL)

SYSTEM: SUBSYSTEM: ASI

Support Hardware J, 12-19-97

FUNCTIONAL CRIT: PHASE(S):

REV & DATE:

DCN & DATE:

HAZARD REF:

S.11, S.03

ANALYSTS:

H. Keefe/ E. Howell

FAILURE MODE:

Structural Failure

FAILURE EFFECT:

Loss of mission and vehicle/crew due to LO2 tank structural failure or debris source

to Orbiter.

TIME TO EFFECT:

Irmediate

FAILURE CAUSE(S):

Improper Manufacture A:

в: Failure of Attaching Hardware

REDUNDANCY SCREENS:

Not Applicable

FUNCTIONAL DESCRIPTION: Provide support for the flexible section of the GO2 pressurization line at the LO2 umbilical cable tray.

EFFECTIVITY FMEA ITEM QTY PART NO. PART NAME CODE(S) 2 LWT-54 & Up 4.4.48.1 80921021037-005 Support (GO2)

REMARKS:			

CRITICAL ITEMS LIST (CIL) CONTINUATION SHEET

SYSTEM:

ASI

SUBSYSTEM:

FMEA ITEM CODE(S):

Support Hardware

4.4.48.1

REV & DATE:

J, 12-19-97

DCN & DATE:

RATIONALE FOR RETENTION

DESIGN:

- A, 6: The support is made from 2219-T62 aluminum alloy sheet. Materials are selected in accordance with MMC-ET-SE16 which assures repetitive conformance of composition and properties.
- A: The support is designed to the required yield (1.1) and ultimate (1.4) safety factors (ET Stress Report 826-2188).
- B: The attaching hardware is selected from the Approved Standard Parts List (ASPL 826-3500). The hardware is installed per STP2014 and torqued using values specified on Engineering drawings. Tensile installation loads are sufficient to provide screening for major flaws in individual fasteners.

TEST:

The Support (GOZ) is certified. Reference MCS MMC-ET-TMO8-L-S168 (LWT-54 thru 88) and MCS MMC-ET-TMO8-L-S524 (LWT-89 & Up).

Vendor:

B: Attaching fasteners are procured and tested to standard drawings 26L23, 26L17 and 33L1.

INSPECTION:

Vendor Inspection - Lockheed Martin Surveillance:

- A, 8: Verify materials selection and verification controls (MMC-ET-SE16, drawing 80921021037 and standard drawings 26L23, 26L17 and 33L1).
- A: Inspect dimensional conformance (drawing 80921021037).

MAF Quality Inspection:

- 8: Inspect that attaching hardware is free from damage (drawing 80921021009 and STP2014).
- A, B: Verify installation and witness torque (drawing 80921021009 and STP2014).
- B: Verify locking feature (drawing 80921021009 and STP2014).

FAILURE HISTORY:

Current data on test failures, unexplained anomalies and other failures experienced during ground processing activity can be found in the PRACA data base.